



325 Industry Drive
Carlisle, Ohio 45005
(513)-932-6248
1-800-977-6872

Industrial Electronic Service

March 2, 2006

DC-25T Count Up/Down Timer


This unit requires 120Volt AC for operation.

When the timer is first connected to power it will set itself to 00:00.

To set Count up timer to zero: make sure timer is off and in the count up mode. Press the reset to last value button.

To set Count Down timer: Make sure timer is off and in the count down mode. Push set minutes button for slow set or both set minutes and reset to last value buttons for fast set. Push reset to last value only if timer is stopped and in countdown timer mode.

Thank you for purchasing DC-Digital clocks.



We Give you the Time!

