



325 Industry Drive  
Carlisle, Ohio 45005  
(513)-932-6248  
1-800-977-6872

# Industrial Electronic Service

March 2, 2006

## DC-25T Count Up Timer

This unit requires 120Volt AC for operation.

When the timer is first connected to power it will set itself to 00:00.

Push start switch to start counting up.

To reset to zero make sure timer is in the stop mode and push the reset button.

Thank you for purchasing DC-Digital clocks.



*We Give you the Time!*

