



325 Industry Drive  
Carlisle, Ohio 45005  
(513)-932-6248  
1-800-977-6872

# Industrial Electronic Service

March 2, 2006

## DC-25T Count Down Timer

This unit requires 120Volt AC for operation.

When the timer is first connected to power it will set itself to 00:00.

To set Count Down timer:

- 1) Make sure timer is in the **Stop** mode.
- 2) Push set minutes button.

OR

- 3) Push reset to last value. Only if a time has been previously set.

Thank you for purchasing DC-Digital.



*We Give you the Time!*

